


Locomotive Collision Test #3
**Grade Crossing Collision of a Freight Locomotive with
a Steel Coil on a Flat Bed Truck**



Test #3: Set-Up




3 Loaded Hopper cars

Test Locomotive
(SD-45, front end
converted to SD-70)

Heavy Highway Vehicle
and Flat Bed Trailer
Loaded with Steel Coils

Collision Speed - 60 mph

Grade Crossing



Bullet Consist

Target Vehicle

60 mph

STATIONARY

Test #3: Pre-Test Pictures



Steel coil aligned with engineer's side collision post




Steel coil trailer alignment with locomotive

Test #3: Post-Test Damage Photos



- Locomotive cabin experienced significant damage
- Anticlimber and endplate not significantly damaged

Test #3: Damage to Collision Post



Front end of post



Rear end of post

- Remainder of collision post including post base and weld bead

Test #3: Outcome

- What did we learn from this test?
 - The alignment of a steel coil at the moment of impact can place a significant load on a single collision post
 - The collision post struck by the massive coil was sheared off just above its weld to the underframe
 - The elevation of the coil just prior to locomotive impact was just above the anticlimber and underframe structure
 - A substantial portion of the hood and cabin was also damaged
 - Crew safety would be affected in this type of collision