


**Locomotive Collision Test #4**  
**Oblique, Offset Collision of a Freight Locomotive with a Loaded,  
Covered Hopper Car**



# Test #4: Set-Up



3 Loaded Hopper cars

Test Locomotive  
(SD-45, front end  
converted to SD-70)

Loaded,  
Covered  
Hopper Car


~30 Loaded Hopper Cars

Collision Speed - 30 mph

Bullet Consist

No. 10 Turnout,  
hopper overlaps  
locomotive by ~3 ft

Target Consist




30 mph

STATIONARY

## Test #4: Pre-Test Photos



- Covered hopper overlaps locomotive by about 3 feet, but does not overlap the engineer's side collision post



## Test #4: Post Test Photos



- Engineer's side windshield corner post significantly damaged during the impact event



## Test #4: Post Test Photos



- Locomotive front truck derailed
- Hood and end plate damaged



## Test #4: Outcome

- What did we learn from this test?
  - Significant damage occurred to the windshield corner post area
  - This damage would be greater with a larger hopper to locomotive overlap or impact speed
  - Some hood and endplate damage also occurred
  - The locomotive's front truck derailed, while the rear truck remained on the track
  - Crew safety would be affected in this type of collision