



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2007-16***

***Union Pacific (UP)
Independence, Missouri
April 7, 2007***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]		1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0407KC008	
2. Name of Railroad Operating Train #2 Union Pacific RR Co. [UP]		2a. Alphabetic Code UP		2b. Railroad Accident/Incident No. 0407KC008	
3. Name of Railroad Operating Train #3 N/A		3a. Alphabetic Code N/A		3b. Railroad Accident/Incident No. N/A	
4. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP]		4a. Alphabetic Code UP		4b. Railroad Accident/Incident No. 0407KC008	
5. U.S. DOT_AAR Grade Crossing Identification Number		6. Date of Accident/Incident Month 04 Day 07 Year 2007		7. Time of Accident/Incident 02:15: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	
8. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
		13. Other (describe in narrative)		Code 03	
9. Cars Carrying HAZMAT 0		10. HAZMAT Cars Damaged/Derailed N/A		11. Cars Releasing HAZMAT N/A	
		12. People Evacuated 0		13. Division Kansas City	
14. Nearest City/Town Independence		15. Milepost (to nearest tenth) 269.1		16. State Abbr Code N/A MO	
		17. County JACKSON			
18. Temperature (F) (specify if minus) 50 F		19. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		20. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1	
		21. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1			
22. Track Name/Number Main Track		23. FRA Track Code Class (1-9, X) 4		24. Annual Track Density (gross tons in millions) 28.56	
		25. Time Table Direction Code 1. North 3. East 2. South 4. 4			
OPERATING TRAIN #1					
26. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
		27. Was Equipment Attended? 1. Yes 2. No 1		Code 1	
		28. Train Number/Symbol IDULA07			
29. Speed (recorded speed, if available) Code R - Recorded E - Estimated 20 MPH R		30. Trailing Tons (gross tonnage, excluding power units) 2619		31. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) e N/A N/A N/A N/A	
		31a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0			
32. Principal Car/Unit		a. Initial and Number UP4323		b. Position in Train 1	
(1) First involved (derailed, struck, etc)		c. Loaded (yes/no) N/A		33. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0	
(2) Causing (if mechanical cause reported)		0		0	
		34. Was this consist transporting passengers? (Y/N) N			
35. Locomotive Units		a. Head End 2		Mid Train b. Manual 0 c. Remote 0	
(1) Total in Train		Rear End d. Manual 0 e. Remote 0		36. Cars (1) Total in Equipment Consist 41	
(2) Total Derailed		0		a. Freight 0 b. Pass. 0 c. Freight 0 d. Pass. 0 e. Caboose 0	
		0		(2) Total Derailed 3	
37. Equipment Damage This Consist 106957		38. Track, Signal, Way, & Structure Damage 850		39. Primary Cause Code H221	
				40. Contributing Cause Code N/A	
41. Engineer/Operators 1		42. Firemen 0		43. Conductors 1	
		44. Brakemen 0		45. Engineer/Operator Hrs 5 Mi 15	
46. Conductor		47. Railroad Employees 0		48. Train Passengers 0	
		49. Other 0		50. EOT Device? 1. Yes 2. No 1	
Casualties to:		51. Was EOT Device Properly Armed? 1. Yes 2. No 1		52. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Fatal		0			
Nonfatal		0			
OPERATING TRAIN #2					
53. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
		54. Was Equipment Attended? 1. Yes 2. No 1		Code 1	
		55. Train Number/Symbol CWLSB06			
56. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH R		57. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits m. Special instructions n. Other than main track e N/A N/A N/A N/A		58a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	

57. Trailing Tons (gross tonnage, excluding power units) 3433	c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other (Specify in narrative) Code(s) e N/A N/A N/A N/A	2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter 0
--	---	---	--	--

59. Principal Car/Unit (1) First involved (derailed, struck, etc) UP8085	a. Initial and Number	b. Position in Train 140	c. Loaded(yes/no) no	60. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0
(2) Causing (if mechanical cause reported) 0	0	0	N/A	61. Was this consist transporting passengers? (Y/N) N

62. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	63. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 2	0	0	0	(1) Total in Equipment Consist 0	0	137	0
(2) Total Derailed 0	0	0	0	(2) Total Derailed 0	0	1	0

64. Equipment Damage This Consist 9322	65. Track, Signal, Way, & Structure Damage 0	66. Primary Cause Code H221	67. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

68. Engineer/Operators 1	69. Firemen 0	70. Conductors 1	71. Brakemen 0	72. Engineer/Operator Hrs 7 Mi 15	73. Conductor Hrs 7 Mi 15
Casualties to:	74. Railroad Employees	75. Train Passengers	76. Other	77. EOT Device? 1. Yes 2. No 2	78. Was EOT Device Properly Armed? 1. Yes 2. No N/A
Fatal	0	0	0	79. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal	0	0	0		

OPERATING TRAIN #3

80. Type of Equipment Consist (single entry)	1. Freight train 2. Passenger train 3. Commuter train	4. Work train 5. Single car 6. Cut of cars	7. Yard/switching 8. Light loco(s) 9. Maint./inspect.car	A. Spec. MoW Equip. Code N/A	81. Was Equipment Attended? 1. Yes 2. No N/A	82. Train Number/Symbol N/A
--	---	--	--	---------------------------------	---	--------------------------------

83. Speed (recorded speed, if available) R - Recorded E - Estimated N/A MPH 0	85. Method(s) of Operation (enter code(s) that apply) a. ATCS b. Auto train control c. Auto train stop d. Cab e. Traffic f. Interlocking	g. Automatic block h. Current of traffic i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	m. Special instructions n. Other than main track o. Positive train control p. Other (Specify in narrative) Code(s) N/A N/A N/A N/A N/A	85a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter N/A
84. Trailing Tons (gross tonnage, excluding power units) 0				

86. Principal Car/Unit (1) First involved (derailed, struck, etc) 0	a. Initial and Number	b. Position in Train 0	c. Loaded(yes/no) N/A	87. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol N/A Drugs N/A
(2) Causing (if mechanical cause reported) 0	0	0	N/A	88. Was this consist transporting passengers? (Y/N) N/A

89. Locomotive Units	a. Head End	Mid Train b. Manual c. Remote	Rear End d. Manual c. Remote	90. Cars	Loaded a. Freight b. Pass.	Empty c. Freight d. Pass.	e. Caboose
(1) Total in Train 0	0	0	0	(1) Total in Equipment Consist 0	0	0	0
(2) Total Derailed 0	0	0	0	(2) Total Derailed 0	0	0	0


91. Equipment Damage This Consist 0	92. Track, Signal, Way, & Structure Damage 0	93. Primary Cause Code N/A	94. Contributing Cause Code N/A
Number of Crew Members		Length of Time on Duty	

95. Engineer/Operators 0	96. Firemen 0	97. Conductors 0	98. Brakemen 0	99. Engineer/Operator Hrs 0 Mi 0	100. Conductor Hrs 0 Mi 0
Casualties to:	101. Railroad Employees	102. Train	103. Other	104. EOT 1. Yes 2. No N/A	105. Was EOT Device Properly 1. Yes 2. No N/A
Fatal	0	0	0	106. Caboose Occupied by Crew? 1. Yes 2. No N/A	
Nonfatal	0	0	0		

Highway User Involved				Rail Equipment Involved			
107. C. Truck-Trailer A. Auto B. Truck D. Pick-Up Truck E. Van	F. Bus G. School Bus H. Motorcycle	J. Other Motor Vehicle K. Pedestrian M. Other (spec. in narrative)	Code N/A	111. Equipment 1. Train(units pulling) 2. Train(units pushing)	3. Train (standing) 4. Car(s)(moving) 5. Car(s)(standing)	6. Light Loco(s) (moving) 7. Light(s) (standing) 8. Other (specify in narrative)	Code N/A
108. Vehicle Speed (est. MPH at impact) N/A	109. geographical 1. North 2. South 3. East 4. West N/A			112. Position of Car Unit in N/A			

110. Position 1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				Code N/A	113. Circumstance 1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User				Code N/A				
114a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials? 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A	114b. Was there a hazardous materials release 1. Highway User 2. Rail Equipment 3. Both 4. Neither				Code N/A				
114c. State here the name and quantity of the hazardous materials released, if any. N/A													
115. Type Crossing 1. Gates 2. Cantilever FLS 3. Standard FLS 4. Wig Wags 5. Hwy. traffic signals 6. Audible Warning 7. Crossbucks 8. Stop signs 9. Watchman 10. Flagged by crew 11. Other (spec. in narr.) 12. None				Code N/A	116. Signaled Crossing (See instructions for codes)				Code N/A	117. Whistle 1. Yes 2. No 3. Unknown		Code N/A	
Code(s)		N/A	N/A	N/A	N/A	N/A	N/A	N/A					
118. Location of Warning 1. Both Sides 2. Side of Vehicle Approach 3. Opposite Side of Vehicle Approach				Code N/A	119. Crossing Warning with Highway Signals 1. Yes 2. No 3. Unknown				Code N/A	120. Crossing Illuminated by Street Lights or Special Lights 1. Yes 2. No 3. Unknown			Code N/A
121. Age 0		122. Driver's Gender 1. Male 2. Female		Code N/A	123. Driver Drove Behind or in Front of and Struck or was Struck by Second Train 1. Yes 2. No 3. Unknown				Code N/A	124. Driver 1. Drove around or thru the Gate 2. Stopped and then Proceeded 3. Did not Stop			Code N/A
125. Driver Passed Highway Vehicle 1. Yes 2. No 3. Unknown				Code N/A	126. View of Track Obscured by (primary obstruction) 1. Permanent Structure 2. Standing Railroad Equipment 3. Passing Train 4. Topography 5. Vegetation 6. Highway Vehicle 7. Other (specify in narrative) 8. Not obstructed								Code N/A
Casualties to:			Killed 0	Injured 0	127. Driver 1. Killed 2. Injured 3. Uninjured				Code N/A	128. Was Driver in the Vehicle? 1. Yes 2. No			Code N/A
129. Highway-Rail Crossing Users			0	0	130. Highway Vehicle Property Damage (est. dollar damage)				0	131. Total Number of Highway-Rail Crossing Users (include driver)			0
132. Locomotive Auxiliary Lights? 1. Yes 2. No				Code N/A	133. Locomotive Auxiliary Lights Operational? 1. Yes 2. No				Code N/A				
134. Locomotive Headlight Illuminated? 1. Yes 2. No				Code N/A	135. Locomotive Audible Warning Sounded? 1. Yes 2. No				Code N/A				

136. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



137. SYNOPSIS OF THE ACCIDENT

On April 7, 2007, at 2:15 p.m., Union Pacific Railroad Company (UP) westbound freight Train Symbol IDULA-07, proceeding at 20 mph, struck the rear unattended distributive power (DPU) locomotive of stopped westbound UP empty unit coal Train Symbol CWLSB9 06. The Train Symbol CWLSB9 06 2-man crew was located in the lead locomotive. The accident occurred at milepost 269.1, near Independence, Missouri, on the UP Kansas City Service Unit, Sedalia Subdivision.

There were no injuries to any crew members. There were five platforms derailed on the fifth and sixth cars of Train Symbol IDULA 07. There was one empty coal car derailed, 126 cars from the head end, on stopped Train Symbol CWLSB9 06. Total reportable damages for this accident were \$117,129.

The cause of the accident was H221 - Automatic block or interlocking signal displaying a stop indication, failure to comply. The inattentiveness on the part of the crew of Train Symbol IDULA-07 resulted in passing a signal displaying stop indication.

The weather was clear, it was daylight, and the temperature was 50 degrees Fahrenheit.

138. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident**Train UP IDULA-07**

The crew of Train Symbol IDULA-07 consisted of a locomotive engineer and a conductor. They first went on duty at 9 a.m., CDT, April 7, 2007, at the UP Yard in Jefferson City, Missouri. This was the home terminal for the engineer and the away-from-home terminal for the conductor. Both crew members received the statutory off-duty period prior to reporting for duty.

Their assigned freight train consisted of 2 locomotives, 41 loads, and 0 empties. All cars were intermodal cars. It was 2,579 feet long, and weighed 2,619 tons. They departed Jefferson City at 9:20 a.m., and were scheduled to travel to Kansas City, Missouri. Freight Train Symbol IDULA-07 had received a Class 1 air brake test at Dupu, Illinois, at 1:20 a.m., on April 7, 2007.

Nearing the accident area, the crew of Train Symbol IDULA-07 observed a clear signal aspect at control point M260. They received an approach indication at Automatic Signal 265.5, indicating proceed prepared to stop before any part of train or engine passes the next signal. Freight trains exceeding 30 mph must immediately reduce to 30 mph. Passenger trains exceeding 45 mph must immediately reduce to 45 mph. The train was already slowing for a 40 mph slow order at milepost 266. As the westbound train approached the accident area, the locomotive engineer was seated at the controls on the north side of the leading locomotive, with the short hood forward. The conductor was standing in the center of the cab near the stairwell.

Train UP CWLSB9 06

The crew of Train Symbol CWLSB9 06 consisted of a locomotive engineer and a conductor. They first went on duty at 7 a.m., CDT, April 7, 2007, at the UP Yard in Jefferson City. This was the away-from-home terminal for both crew members. Both crew members received the statutory off-duty period prior to reporting for duty.

Their assigned freight train consisted of 2 lead locomotives, 0 loads, 137 empties, and 1 DPU on the rear. All cars were empty coal cars. It was 7,545 feet long, and weighed 3,433 tons and departed Jefferson City at approximately 7:30 a.m., scheduled to travel to Kansas City. The extended-haul unit coal train had received a Class 1 air brake test at North Platte, Nebraska, at 2:10 a.m., on April 4, 2007.

Westbound Train Symbol CWLSB9 06 was stopped for approximately 14 minutes prior to the accident at the stop signal of control point M271. The locomotive engineer was seated at the controls on the north side of the leading locomotive, with

the short hood forward. The conductor was seated on the south side of the leading locomotive. Their rear DPU was about three to five cars beyond and west of Automatic Signal 269.1, which was displaying a red stop indication.

In this area, the track is tangent from milepost 267.3 to milepost 267.7. Then there is a 1-degree 11.2-minute curve to the right to milepost 268.2. The track is tangent again to milepost 268.78, where there is a 1-degree 14.6-minute curve to the left to milepost 269.3. The grade is 1 percent ascending westward.

The railroad timetable direction of the train is west. The geographic direction is north. Timetable directions are used throughout this report.

The Accident

Train Symbol IDULA-07 approached the accident area at 30 mph. The engineer and conductor stated they were engaged in a discussion about operating rules and train handling, and were distracted regarding the operation of the train. The engineer stated the conductor did not call "cab red zone" which requires the crew to suspend all conversation not directly related to the operation of the train. The conductor stated she did call "cab red zone." During this lapse in attentiveness, Train Symbol IDULA-07 was operated by the red signal, although placed in emergency by the engineer prior to arriving at the signal, and struck the rear unattended DPU of stopped Train Symbol CWLSB9 06 at 20 mph. There were no injuries to either crew and no hazardous materials were released.

As a result of the collision, five platforms of cars 6 and 7 on Train Symbol IDULA-07 derailed. There was one car derailed in Train Symbol CWLSB9 06, located 126 from the head end of the train.

Total reportable damages for this accident were \$117,129.

Analysis and Conclusions

Analysis

Post-accident toxicological testing was performed on the conductor and engineer of Train Symbol IDULA-07. Results for both crew members were negative.

Post-accident toxicological testing was not performed on the crew of Train Symbol CWLSB9 06.

There were no tests performed on the equipment, track, or signal system because the crew claimed responsibility for the accident.

Conclusions

The 2-member crew of Train Symbol IDULA-07 was distracted from the operation of their train by conversation. The accident occurred because the inattentive crew failed to stop their train prior to passing a signal displaying stop indication.

Probable Cause and Contributing Factors

The cause is determined by the FRA to be H221 - Automatic block or interlocking signal displaying a stop indication, failure to comply.