



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-14***

***Amtrak (ATK)/Union Pacific (UP)
Oxnard, California
February 14, 2005***

Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Amtrak [ATK]		1a. Alphabetic Code ATK		1b. Railroad Accident/Incident No. 95533	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A	
3. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP]		3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. 0205LA019	
4. U.S. DOT_AAR Grade Crossing Identification Number 745854B		5. Date of Accident/Incident Month: 02 Day: 14 Year: 2005		6. Time of Accident/Incident 04:35: <input type="checkbox"/> AM <input checked="" type="checkbox"/> PM	

7. Type of Accident/Incident (single entry in code box)					
1. Derailment	2. Head on collision	3. Rear end collision	4. Side collision	5. Raking collision	6. Broken Train collision
7. Hwy-rail crossing	8. RR grade crossing	9. Obstruction	10. Explosion-detonation	11. Fire/violent rupture	12. Other impacts
13. Other (describe in narrative)					07

8. Cars Carrying HAZMAT 0	9. HAZMAT Cars Damaged/Derailed 0	10. Cars Releasing HAZMAT 0	11. People Evacuated 0	12. Division Los Angeles
------------------------------	--------------------------------------	--------------------------------	---------------------------	-----------------------------

13. Nearest City/Town Oxnard		14. Milepost (to nearest tenth) 405.2		15. State Abbr Code N/A CA		16. County VENTURA	
---------------------------------	--	--	--	-------------------------------	--	-----------------------	--

17. Temperature (F) (specify if minus) 65 F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 2		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 2		20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 1	
--	--	--	--	---	--	---	--

21. Track Name/Number Main		22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 10		24. Time Table Direction Code 1. North 3. East 1	
-------------------------------	--	--	--	---	--	--	--

OPERATING TRAIN #1

25. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		7. Yard/switching		A. Spec. MoW Equip. Code		26. Was Equipment Attended?		27. Train Number/Symbol	
3. Commuter train		5. Single car		6. Cut of cars		8. Light loco(s).		9. Maint./inspect.car		1. Yes 2. No 2 1		775-14	

28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 79 MPH R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits						30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter					
29. Trailing Tons (gross tonnage, excluding power units) 0		e		N/A		N/A		N/A		N/A		0	

31. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded (yes/no)		32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.					
(1) First involved (derailed, struck, etc)		N/A		1		N/A		Alcohol		Drugs		0 0	
(2) Causing (if mechanical cause reported)		0		0		N/A		33. Was this consist transporting passengers? (Y/N)				Y	

34. Locomotive Units		a. Head End		b. Mid Train		c. Rear End		35. Cars		a. Freight		b. Pass.		c. Freight		d. Pass.		e. Caboose	
(1) Total in Train		1		0		0		0		0		5		0		0		0	
(2) Total Derailed		0		0		0		0		0		0		0		0		0	

36. Equipment Damage This Consist		81574		37. Track, Signal, Way, & Structure Damage		1500		38. Primary Cause Code		M302		39. Contributing Cause Code		H304	
-----------------------------------	--	-------	--	--	--	------	--	------------------------	--	------	--	-----------------------------	--	------	--

40. Engineer/Operators N/A				41. Firemen 0		42. Conductors 1		43. Brakemen 1		44. Engineer/Operator Hrs 2 Mi 25				45. Conductor Hrs 2 Mi 25			
-------------------------------	--	--	--	------------------	--	---------------------	--	-------------------	--	--------------------------------------	--	--	--	------------------------------	--	--	--

Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		49. EOT Device? 1. Yes 2. No 2				50. Was EOT Device Properly Armed? 1. Yes 2. No N/A			
Fatal		0		0		0		51. Caboose Occupied by Crew? 1. Yes 2. No				2			
Nonfatal		N/A		0		0									


OPERATING TRAIN #2

52. Type of Equipment Consist (single entry)		1. Freight train		4. Work train		7. Yard/switching		A. Spec. MoW Equip. Code		53. Was Equipment Attended?		54. Train Number/Symbol	
3. Commuter train		5. Single car		6. Cut of cars		8. Light loco(s).		9. Maint./inspect.car		1. Yes 2. No N/A		N/A	

55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track						57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable	
--	--	---	--	--	--	--	--	--	--

56. Trailing Tons (gross tonnage, excluding power units)		0		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A	
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		Alcohol		Drugs	
(1) First involved (derailed, struck, etc)		0		0		N/A				N/A		N/A	
(2) Causing (if mechanical cause reported)		0		0		N/A		60. Was this consist transporting passengers? (Y/N)				N/A	
61. Locomotive Units		a. Head End		Mid Train		Rear End		62. Cars		Loade		Empty	
				b. Manual		c. Remote				a. Freight		b. Pass.	
										c. Freight		d. Pass.	
										e. Caboose			
(1) Total in Train		0		0		0		(1) Total in Equipment Consist		0		0	
(2) Total Derailed		0		0		0		(2) Total Derailed		0		0	
63. Equipment Damage		This Consist		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		N/A		66. Contributing Cause Code	
0												N/A	
Number of Crew Members						Length of Time on Duty							
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor			
0		0		0		0		Hrs 0 Mi 0		Hrs 0 Mi 0			
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?			
Fatal		0		0		0		1. Yes 2. No N/A		1. Yes 2. No N/A			
Nonfatal		0		0		0		78. Caboose Occupied by Crew?		N/A			
								1. Yes 2. No					
Highway User Involved						Rail Equipment Involved							
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving)		Code	
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				C		1. Train(units pulling)		4. Car(s)(moving)		7. Light(s) (standing)			
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)						2. Train(units pushing)		5. Car(s)(standing)		8. Other (specify in narrative)		1	
80. Vehicle Speed		81. Direction geographical		Code		84. Position of Car Unit in Train		1					
(est. MPH at impact) 0		1. North 2. South 3. East 4. West		3									
82. Position		Code		85. Circumstance		Code		1. Rail Equipment Struck Highway User		1			
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped		2				2. Rail Equipment Struck by Highway User							
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?		Code		86b. Was there a hazardous materials release by		Code		1. Highway User 2. Rail Equipment 3. Both 4. Neither		4			
1. Highway User 2. Rail Equipment 3. Both 4. Neither		4											
86c. State here the name and quantity of the hazardous materials released, if any. N/A													
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code	
2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)		89. Whistle Ban		Code	
3. Standard FLS		6. Audible		9. Watchman		12. None				1. Yes		2. No	
Code(s)		01		02		03		05		06		07	
								N/A				3. Unknown	
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code			
1. Both Sides				1. Yes		1		1. Yes		1			
2. Side of Vehicle Approach				2. No				2. No					
3. Opposite Side of Vehicle Approach		1		3. Unknown				3. Unknown					
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code	
52		1. Male		2		1. Yes 2. No 3. Unknown		1		1. Drove around or thru the Gate		4. Stopped on Crossing	
		2. Female								2. Stopped and then Proceeded		5. Other (specify in narrative)	
										3. Did not Stop		4	
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code		8					
1. Yes 2. No 3. Unknown		2		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)									
				2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed									
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code	
		0		0		1. Killed 2. Injured 3. Uninjured		3		1. Yes		2. No	
						102. Highway Vehicle Property Damage (est. dollar damage)		0		103. Total Number of Highway-Rail Crossing Users (include driver)		1	
104. Locomotive Auxiliary Lights?		Code		105. Locomotive Auxiliary Lights Operational?		Code							
1. Yes 2. No		1		1. Yes 2. No		1							
106. Locomotive Headlight Illuminated?		Code		107. Locomotive Audible Warning Sounded?		Code							
1. Yes 2. No		1		1. Yes 2. No		1							

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.
HQ-14-2005.jpg



109. SYNOPSIS OF THE ACCIDENT

Synopsis of the Accident:

On Monday, February 14, 2005, at 4:30 p.m. PST, an Amtrak passenger train struck a tractor/semi-trailer at a highway-rail crossing in the City of Oxnard CA. The accident occurred at Rose Avenue, crossing no. DOT# 745854B, milepost 405.25 on UP's Los Angeles Area, Santa Barbara Subdivision.

The accident involved a northbound Amtrak train # 775 being pulled by lead locomotive no. 458 traveling at 79 mph, which impacted a tractor/semi-trailer carrying frozen strawberries and was stopped with the trailer across the tracks at the intersection of Rose Avenue and 5th St. No other vehicles were damaged in this incident.

Amtrak Timetable information states train # 775 originates at 12:00 p.m. in San Diego, CA., with final destination stop at 9:20 p.m. in Paso Robles, CA. Weather was partly cloudy skies prior to sunset and temperature was 65 degrees Fahrenheit.

Four Amtrak passengers complained of minor injuries; two were taken to area hospitals. The engineer sustained bruises on the upper part of both arms but did not request treatment. An unspecified next-day injury was claimed by the Assistant Conductor (February 15, 2005). The status of the injured passengers and Assistant Conductor are not known at this time. The driver of the tractor/semi-trailer was not injured.

The Rose Avenue accident site is a geographic north-south highway-rail grade crossing equipped with warning devices and pre-empted traffic signals at the adjacent intersection with 5th Street. Vehicular speed limit for Rose Avenue is 40 mph. Timetable track designation is north and south for railroad traffic but is geographic east-west at the site. The warning devices in service have light units mounted on cantilevers for northbound and southbound vehicle traffic. There are two warning light units with gate arms and gongs, each mounted on curbs and island sites for each direction of vehicle traffic. Rose Avenue has four southbound lanes and three northbound lanes approaching the grade crossing. Track structure approaching the grade crossing is tangent track for about four miles. It has a 0.20 percent descending grade for about a quarter mile to a 0.0 percent grade at the grade crossing/point of impact. A pre-empted circuit to the traffic signals comes off the break from the Crossing Relay (XR) operated by a Safetran Grade Crossing Predictor 3000D2 (GCP-3000) unit with a set warning time programed in the unit for 30 seconds. Traffic signals cue time allows seven seconds after warning device activation for a red signal to change to green to clear southbound vehicle traffic at Rose. At 15 seconds the traffic light changes from green to yellow to red clocked in 5 second intervals. The full cycle is 20 seconds. There is good visibility for both vehicle and trains in this area. Warning time down-loaded from the event recorder was 25 seconds. The investigation thus far concludes the warning systems operated as intended.

Damage estimates of the track and signal is \$1,500; and equipment \$8,574.00.

Probable cause: The driver of the tractor/semi-trailer stopped and failed to obey the warning signals and did not yield to the oncoming train.

110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

Circumstances Prior to the Accident:

Amtrak passenger train symbol 775-14 originated in San Diego, with final destination at Paso Robles, CA. Train 775 was scheduled to arrive at Union Station in Los Angeles for a passenger stop and to make a crew change. After statutory rest time the conductor first went on duty at 1:55 pm and Engineer at 2:10 pm P.S.T. on February 14, 2005.

Locomotive number 458 on train 775 was given an initial departure test in the Los Angeles Terminal Station at 3:00 am on February 14, 2005 and was symboled 566 earlier for a trip from Los Angeles to San Diego, CA. After a symbol change from 566 to 775 in San Diego, CA., the train returned to Los Angeles, CA. The crew then boarded train 775 and departed from Los Angeles Union Station on time at 2:55 pm.

The Accident:

Train 775

Train 775 was being operated at 79 mph approaching the accident area. The engineer had good visual sight of the crossing and saw that a large truck was fouling the track at the grade crossing. The engineer sounded the horn at the whistle sign when she saw a truck come to a rolling stop with the trailer end on the track. The engineer noticed the warning system lights were operating with the gates down. The engineer became aware of the impending collision, 1,000 feet in advance then placed the emergency brakes on the train and got behind the seat in a position with her hands behind her head and prepared for the impact.

Highway Vehicle

The semi-trailer truck with driver and had just been loaded with frozen strawberries en-route to a unknown destination and was headed geographical south on Rose Avenue to the accident area. The truck was stopped passed the marked limit lines at the grade crossing. The warning devices began operating and the truck pulled forward just as the warning gates had lowered on the truck. The truck continued slowly across the tracks, then stopped with the rear of the trailer on the tracks. The train struck the trailer on the left side, separated it from the front cab and sent the commodities everywhere. The collision caused the passenger cars to separate from the lead locomotive and the train stopped 1/4 of a mile passed the accident site. The locomotive had extensive damage and had to be place at a nearby spur track.

As soon as the engineer found it was safe, she grabbed the radio and transmitted an emergency message to the dispatcher. Then she communicated with the conductor to see if every thing was "ok" and to check on passengers.

Emergency vehicles from the Oxnard Fire and Police Department arrived and started evacuation of passengers and treated injured at the scene. Four passengers complained about minor injuries, two were taken to a local hospital.

Analysis and Conclusions

Analysis

The driver of the truck was a 52 year old female. There were no other persons in the truck. The driver was employed by Action Carriers, Sioux Falls, South Dakota. The highway-rail grade crossing is equipped with warning lights, gates, bell, and circuit for pre-emption of adjacent traffic signals.

Video showed the truck driver had stopped beyond the Double white limit line for a red traffic signal at the adjacent intersection of Rose Avenue and Fifth St. The warning system began to activate and the gates began to lower. The truck driver got confused with the activation and the cued green traffic signal and pulled her truck with the gate lowered on it. After 15 seconds minimum cue time for the clear out green traffic signal, the signal cycled to red and did not allow time for the large truck to clear the tracks. There is no advance warning sign for southbound vehicular traffic in advance of this grade crossing. Pavement markings are clearly visible. This area is maintain by the City of Oxnard.

The active warning system was tested after the accident and in the present of an FRA signal and train control inspector. The warning system function as intended.

The lead locomotive was equipped with headlight, the auxiliary lights, and the audible warning device required by Federal regulations.

The locomotive was also equipped with a speed indicator and an event recorder as required. The train engineer, and a crew member from a nearby work train were the only witness to the accident, and they have no information that could determine why the truck stopped on the tracks. The truck driver was issued a citation for failure to yield at a grade crossing.

In review of the Oxnard Police Report, the investigating officer issued a notice to arrear citation # 388567 for violation of California Vehicle Code 22451 (a)(1) Railroad crossing, failure to stop for signal device or closely approaching train.

Probable Cause & Contributing Factors

The accident occurred because the truck driver failed to stop before the marked white limit line on a paved street in advance of the highway-rail crossing at grade, and yield to an oncoming train. Driver confusion with near-by traffic signals minimum green clear out cue time may have been a contributing factor.

The FRA determined that the contributing cause was (M304). Highway user cited for violation of highway-rail grade crossing traffic laws.

Probable Cause (M302) Highway user inattentiveness.