



***Federal Railroad Administration
Office of Safety
Headquarters Assigned
Accident Investigation Report
HQ-2005-68***

***Union Pacific (UP)
Heber, California
August 20, 2005***


Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP]		1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 0805LA027	
2. Name of Railroad Operating Train #2 Union Pacific RR Co. [UP]		2a. Alphabetic Code UP		2b. Railroad Accident/Incident No. 0805LA027	
3. Name of Railroad Responsible for Track Maintenance (single entry) Union Pacific RR Co. [UP]		3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. 0805LA027	
4. U. S. DOT-AAR Grade Crossing Identification Number N/A		5. Date of Accident/Incident month 08 day 21 year 2005		6. Time of Accident/Incident 10:30: AM <input type="checkbox"/> PM <input checked="" type="checkbox"/>	
7. Type of Accident/Incident (single entry in code box)					
1. Derailment		4. Side collision		7. Hwy-rail crossing	
2. Head on collision		5. Raking collision		8. RR grade crossing	
3. Rear end collision		6. Broken Train collision		9. Obstruction	
				10. Explosion-detonation	
				11. Fire/violent rupture	
				12. Other impacts	
				13. Other (describe in narrative)	
				Code 12	
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0	
				11. People Evacuated 0	
				12. Division Los Angeles	
13. Nearest City/Town Heber		14. Milepost (to nearest tenth) 704.0		15. State Code CA	
				16. County IMPERIAL	
17. Temperature (F) (specify if minus) 90 °F		18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark 4		19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow 1	
				20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry 3	
21. Track Name/Number Heber Passing Track		22. FRA Track Code Class (1-9, X) 1		23. Annual Track Density (gross tons in millions) .00	
				24. Time Table Direction Code 1. North 3. East 2. South 4. West 3	
OPERATING TRAIN # 1					
25. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		8. Light loco(s).	
				9. Maint./inspect. car	
				A. Spec. MoW Equip. Code	
				26. Was Equipment Attended? Code 1. Yes 2. No 2	
				27. Train Number/Symbol LKE34-19	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 0 MPH R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track rules c. Auto train stop i. Time table/train orders o. Positive train control d. Cab signals j. Track warrant control p. Other (specify in narrative) e. Traffic control k. Direct traffic control Code(s) f. Interlocking l. Yard limits		30a. Remotely Controlled Locomotive? 0= Not a remotely controlled operation 1 = Remote control portable transmitter 2 = Remote control tower operation 3 = Remote control portable transmitter - more than one remote control transmitter 0	
29. Trailing Tons (gross tonnage, excluding power units) 3,505				i n N/A N/A N/A	
31. Principal Car/Unit (1) First involved (derailed, struck, etc) CSXT475255		a. Initial and Number		b. Position in Train 1	
(2) Causing (if mechanical cause reported) 0		0		c. Loaded (yes/no) no	
				32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box. Alcohol 0 Drugs 0	
				33. Was this consist transporting passengers? (Y/N) N	
34. Locomotive Units		a. Head End		Mid Train	
		b. Manual		c. Remote	
		d. Manual		e. Remote	
(1) Total in Train 0		0		0	
(2) Total Derailed 0		0		0	
				35. Cars	
				a. Freight	
				b. Pass.	
				c. Freight	
				d. Pass.	
				e. Caboose	
				(1) Total in Equipment Consist 0	
				(2) Total Derailed 0	
				0	
				0	
				0	
				0	
36. Equipment Damage This Consist \$22,434.00		37. Track, Signal, Way, & Structure Damage \$0.00		38. Primary Cause Code H404	
				39. Contributing Cause Code H402	
Number of Crew Members			Length of Time on Duty		
40. Engineers/Operators 0		41. Firemen 0		42. Conductors 0	
43. Brakemen 0		44. Engineer/Operator Hrs: 0 Mins: 0		45. Conductor Hrs: 0 Mins: 0	
Casualties to:		46. Railroad Employees		47. Train Passengers	
48. Other		49. EOT Device?		50. Was EOT Device Properly Armed?	
Fatal 0		1. Yes 2. No 2		1. Yes 2. No N/A	
Nonfatal 0		51. Caboose Occupied by Crew? 1. Yes 2. No N/A			
OPERATING TRAIN # 2					
52. Type of Equipment Consist (single entry)		1. Freight train		4. Work train	
2. Passenger train		5. Single car		7. Yard/switching	
3. Commuter train		6. Cut of cars		8. Light loco(s).	
		9. Maint./inspect. car		A. Spec. MoW Equip. Code	
				53. Was Equipment Attended? Code 1. Yes 2. No 1	
				54. Train Number/Symbol LKE35-21	
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated 23 MPH R		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track rules c. Auto train stop i. Time table/train orders o. Positive train control d. Cab signals j. Track warrant control p. Other (specify in narrative) e. Traffic control k. Direct traffic control Code(s) f. Interlocking l. Yard limits		57a. Remotely Controlled Locomotive? 0= Not a remotely controlled operation 1 = Remote control portable transmitter 2 = Remote control tower operation 3 = Remote control portable transmitter - more than one remote control transmitter 0	
56. Trailing Tons (gross tonnage, excluding power units) 3,857				j n N/A N/A N/A	

OPERATING TRAIN # 2 (CONTINUED)

58. Principal Car/Unit (1) First involved (derailed, struck, etc)		a. Initial and Number UP(SP)2658		b. Position in Train 1		c. Loaded (yes/no) N/A		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.			Alcohol 0	Drugs 0					
(2) Causing (if mechanical cause reported)		0		0		N/A		60. Was this consist transporting passengers? (y/n)			N						
61. Locomotive Units		a. Head End	Mid Train b. Manual c. Remote		Rear End d. Manual e. Remote		62. Cars			Loaded a. Freight b. Pass.		Empty c. Freight d. Pass.		e. Caboose			
(1) Total in Train		1	0 0		0 0		(1) Total in Equipment Consist			30	0	9	0	0			
(2) Total Derailed		0	0 0		0 0		(2) Total Derailed			2	0	1	0	0			
63. Equipment Damage This Consist		\$8,946		64. Track, Signal, Way, & Structure Damage		\$4,000		65. Primary Cause Code		H404		66. Contributing Cause Code		H402			
Number of Crew Members						Length of Time on Duty											
67. Engineers/ Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor							
1		0		1		1		Hrs: 2 Mins: 30		Hrs: 2 Mins: 30							
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?							
Fatal		0		0		0		1. Yes 2. No 1		1. Yes 2. No 1							
Nonfatal		3		0		0		78. Caboose Occupied by Crew? 1. Yes 2. No N/A									
Highway User Involved						Rail Equipment Involved											
79. Type		C. Truck-Trailer		F. Bus		J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing)		6. Light Loco(s) (moving) Code			
A. Auto		D. Pick-Up Truck		G. School Bus		K. Pedestrian				1. Train (units pulling)		4. Car(s) (moving)		7. Light Loco(s) (standing)			
B. Truck		E. Van		H. Motorcycle		M. Other (spec. in narrative)		N/A		2. Train (units pushing)		5. Car(s) (standing)		8. Other (specify in narrative) N/A			
80. Vehicle speed (est. MPH at impact)		N/A		81. Direction (geographical)		Code				84. Position of Car Unit in Train		N/A					
82. Position		1. Stalled on Crossing		2. Stopped on Crossing		3. Moving Over Crossing		4. Trapped		Code		85. Circumstance		Code			
		N/A		N/A		N/A		N/A				1. Rail Equipment Struck Highway User		2. Rail Equipment Struck by Highway User N/A			
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?		Code								86b. Was there a hazardous materials release by		Code					
1. Highway User		2. Rail Equipment		3. Both		4. Neither		N/A		1. Highway User		2. Rail Equipment		3. Both 4. Neither N/A			
86c. State here the name and quantity of the hazardous materials released, if any.		N/A															
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code	
Warning		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other (spec. in narr.)		(See instructions for codes)				1. Yes			
Code(s)		N/A		N/A		N/A		N/A		N/A		N/A		2. No		3. Unknown N/A	
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code							
1. Both Sides				1. Yes		N/A		1. Yes		N/A		2. No		3. Unknown		N/A	
2. Side of Vehicle Approach				2. No				2. No				3. Unknown					
3. Opposite Side of Vehicle Approach		N/A		3. Unknown				3. Unknown									
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code					
0		1. Male		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate		4. Stopped on Crossing					
		2. Female								2. Stopped and then Proceeded		5. Other (specify in narrative)				N/A	
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code			
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure		3. Passing Train		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A			
				2. Standing Railroad Equipment		4. Topography		5. Vegetation				7. Other (specify in narrative)					
				2. Standing Railroad Equipment				6. Highway Vehicles				8. Not obstructed					
Casualties to:		Killed		Injured				102. Highway Vehicle Property Damage (est. dollar damage)		\$0		103. Total Number of Highway-Rail Crossing Users (include driver)		0			
101. Highway-Rail Crossing Users		0		0													
104. Locomotive Auxiliary Lights?		Code		105. Locomotive Auxiliary Lights Operational?		Code											
1. Yes		2. No		N/A		1. Yes 2. No		N/A		1. Yes 2. No		N/A					
106. Locomotive Headlight Illuminated?		Code		107. Locomotive Audible Warning Sounded?		Code											
1. Yes		2. No		N/A		1. Yes 2. No		N/A		1. Yes 2. No		N/A					

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



109. SYNOPSIS OF THE ACCIDENT

On August 21, 2005, at 10:30 p.m. PDT, an eastbound Union Pacific (UP) freight train LKE35-21 (Train # 2) operating on main line track and consisting of a single locomotive with 39 cars impacted an unattended standing cut of cars on the Heber passing track (MP704.0) at a recorded speed of 23 mph. The collision derailed three cars of Train # 2 and five of 22 cars set out by UP freight train LKE34-19 (Train #1) to derail. The three crew members of Train # 2 were transported by ambulance to a hospital where they were treated for multiple lacerations of their heads, arms and chests. There was no release of hazardous materials and no evacuation ordered.

UP's Calexico Subdivision operates in a timetable east-west direction between Niland Junction, MP 667.9 and Calexico, MP 708.5 in Imperial County, California. The method of operation is Track Warrant Authority (TWC), non-signalized territory. The dispatcher is located in San Bernardino, California. The subdivision is single main track with sidings and yard tracks. The maximum timetable speed at the point of impact is 10 mph, while main track speed is 40mph.

Damage was listed as follows: equipment, \$31,380, track, \$4,000.

At the time of the accident it was dark but clear and the temperature was 90 degrees F.

The accident was caused by the failure of Train #1's crew to re-line a switch back to the main track after completing switching operations on the Heber passing track and failure to comply with Timetable Special Instructions, Conductor's Report Form, TT/SSi Rule 1.47, Duties of Crew Members.

110. NARRATIVE

Circumstances prior to the accident:

UP Train # 1 (LKE34-19)

On August 19, 2005, a crew consisting of an engineer and brakeman went on duty at 8:00 a.m. PDT at the El Centro (CA) Yard. The conductor received a late call and was on duty at 8:45 a.m. All three crew members received the statutory time off duty prior to reporting for duty.

At approximately 9:15 a.m., the crew received the required job briefing and paperwork and was instructed to run lite locomotives to Calexico, pick up interchange and industry cars in El Toro and switch at Heber, CA. The crew departed El Centro at 10:00 a.m., railroad west. In Calexico, they made some switching moves to assemble their train, made an air test, and departed Calexico with 68 cars, 12 loads and 56 empties for their return to Heber. Train #1 operated railroad east from Calexico to Heber.

Geographically, El Centro is approximately 14.6 miles north of Heber and Calexico is approximately 4.5 miles south of Heber. All directions used in this report are UP timetable directions. Approaching the accident site, the track is tangent for over one-half mile and 0.35% descending grade. The area is rural.

During the trip to Heber, the engineer was at the controls of the locomotive and the other crew members were seated on the opposite side of the cab. The crew discussed the switching moves while en route. Upon arrival, the train stopped at the east end of Heber on the main track and cut the El Centro cars away from the locomotives. The brakeman got off the train, uncoupled the locomotives and applied hand brakes. The engineer, accompanied by the conductor, operated the lite locomotives on the main track west to the west end of Heber. The brakeman then lined and locked the switches at the east end of the passing track for the main track. The train would back up later to couple onto the cars left on the main track.

Following various switching moves, 22 cars were set on the Heber passing track. During the switching, the brakeman contacted the conductor, advised him that a crew van had arrived and asked if he needed any help applying the hand brakes on the cars on the passing and storage tracks. The conductor said he did not need help so the brakeman waited in the van for the conductor. After applying hand brakes on the cars, the conductor joined the brakeman in the van where they discussed the next switching moves and were taken to the head end of the train. After completing the work at Heber, the crew departed by train to do other industry work between Heber and El Centro.

UP Train # 2 (LKE35-21)

On August 21, 2005, the crew consisting of an engineer, conductor and a brakeman, went on duty at 8:00 p.m. PDT at the El Centro Yard. All three crew members received the statutory time off prior to reporting for duty. At approximately 8:15 p.m., they received their required paper work and a job briefing from the manager on duty. They were instructed to perform switching operations in the El Centro Yard and proceed to Calexico to set out the interchange cars.

Train # 2 departed El Centro at approximately 10:00 p.m. with a single locomotive and 39 cars. The train was operated railroad east with the engineer at the controls of the locomotive and the other crew members seated on the opposite side of the cab. As the train approached Heber, the locomotive engineer sounded the whistle at the quarter-mile whistle board for the Correll Road Crossing (MP 703.47) at a speed of 30 mph. While in the middle of Correll Road, the engineer asked the conductor if the switch at the west end of Heber was lined for the siding. Both the engineer and the conductor noticed that the switch was lined from the main to the siding. The engineer placed the train air brake controls in emergency.

The conductor yelled to the crew, "We're going to go into the siding and strike the cars! Lay down on the floor with your feet toward the front of the locomotive!" As the train was slowing down, it left the main track, entered the Heber passing track and collided with the cut of cars set out earlier by Train #1.

The Accident:

At 10:30 p.m. PDT, August 21, 2005, Train #2 collided with an unattended standing cut of cars on the Heber passing track (MP704.0) at a recorded speed of 23 mph. The collision derailed three cars of Train # 2 and five cars of Train # 1. All three crew members of Train # 2 were injured.

At impact, the engineer was laying down on the right side of the cab floor, the conductor was laying down in the middle and the brakeman was laying on the left side of the cab. After the collision, the conductor contacted the train dispatcher via radio and informed him of the accident. The crew helped each other out of the locomotive.

Paramedics from Heber and El Centro Fire Departments and Union Pacific managers arrived a short time later. After the crew members were examined by paramedics, they were transported to Pioneer Memorial Hospital in Brawley, California.

Post Accident Investigation:

On August 23, 2005, at 9:30 a.m. PDT, a California Public Utilities Commission (CPUC) Operating Practices Inspector interviewed the conductor and brakeman of Train # 1. In the interview the conductor stated he was sure he had lined the main track switch and derail for main line movement at Heber. The railroad did not conduct reasonable cause testing on the crew of Train #1.

The investigation revealed the conductor of Train # 1 failed to release his Track Warrant at the end of his shift. It was not released until Sunday, August 21, 2005, at 7:04 a.m.

The railroad held a disciplinary investigation on Train #1's conductor and brakeman for General Code of Operating Rules violations for failure to comply with order/track warrant/track bulletin/timetable and motor car or on-track equipment rules. The conductor was allowed to take remedial (CORE) training and the brakeman received an admonishment. UP found the engineer was not to blame and did not conduct a discipline hearing on him.

Train #2's engineer was working light duty as of October 3, 2005 and returned to full duty on January 23, 2006. The conductor was working light duty as of November 1, 2005, received physical therapy and was released to full duty on February 17, 2006. The brakeman was expected to return to full duty on March 1, 2006.

After the accident, UP managers conducted an around-the-clock Safety Blitz to inform all Train, Yard and Engine (TY&E) personnel of the Revised System Special Instructions (TT/SSI). Throughout the week of September 6, 2005, CPUC and FRA Operating Practices Inspectors and UP managers conducted unannounced testing on TY&E crews on trains and in job briefings in the El Centro area.

Track Damage: \$4,000
Equipment Damage Estimate: \$31,380.

Operating Practices Follow-up: During the week of January 9, 2006, FRA and CPUC inspectors conducted an Emergency Order 24 and Operating Rules audit with UP operating officers in the El Centro area. Testing was conducted for specific rules that contributed to the accident, including general orders, general bulletins and circulars, use of switches and track warrant control. The audit disclosed employees were in compliance with EO 24 and UP General Code of Operating Rules.

Probable Cause:

The accident was caused by the failure of Train #1's crew to re-line a switch back to the main track after completing switching operations on the Heber passing track and failure to comply with Timetable Special Instructions, Conductor's Report Form, TT/SSI Rule 1.47, Duties of Crew Members.