



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2005-88***

***Union Pacific (UP)  
Broadwater, Nebraska  
October 5, 2005***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***




*Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2005-88*

*Union Pacific (UP)  
Broadwater, Nebraska  
October 5, 2005*

1. Name of Railroad Operating Train #1 Union Pacific RR Co. [UP ]		1a. Alphabetic Code UP		1b. Railroad Accident/Incident No. 1005NP002	
2. Name of Railroad Operating Train #2 N/A		2a. Alphabetic Code N/A		2b. Railroad Accident/Incident N/A	
3. Name of Railroad Responsible for Track Maintenance: Union Pacific RR Co. [UP ]		3a. Alphabetic Code UP		3b. Railroad Accident/Incident No. 1005NP002	
4. U.S. DOT_AAR Grade Crossing Identification Number		5. Date of Accident/Incident Month   Day   Year 10   05   2005		6. Time of Accident/Incident 05:10: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM	
7. Type of Accident/Incident (single entry in code box)		1. Derailment 2. Head on collision 3. Rear end collision		4. Side collision 5. Raking collision 6. Broken Train collision	
		7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction		10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts	
				13. Other (describe in narrative)   01	
8. Cars Carrying HAZMAT 0	9. HAZMAT Cars Damaged/Derailed 0	10. Cars Releasing HAZMAT 0	11. People Evacuated 0	12. Division North Platte	
13. Nearest City/Town Bridgeport		14. Milepost (to nearest tenth) 108.95	15. State Abbr Code N/A   NE	16. County MORRILL	
17. Temperature (F) (specify if minus) 36 F	18. Visibility (single entry) Code 1. Dawn 3. Dusk 2. Day 4. Dark   4	19. Weather (single entry) Code 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow   1	20. Type of Track Code 1. Main 3. Siding 2. Yard 4. Industry   1		
21. Track Name/Number Main Track No. 2		22. FRA Track Code Class (1-9, X) 4	23. Annual Track Density (gross tons in millions) 223	24. Time Table Direction Code 1. North 3. East   3	
<b>OPERATING TRAIN #1</b>					
25. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		A. Spec. MoW Equip. Code 1	
				26. Was Equipment Attended? 1. Yes 2. No   1	
				27. Train Number/Symbol CCDCB903	
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated   47 MPH   R		30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter   0
29. Trailing Tons (gross tonnage, excluding power units) 17181		d	e	N/A	N/A
31. Principal Car/Unit	a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.	
(1) First involved (derailed, struck, etc)	N/A	98	yes	Alcohol	Drugs
(2) Causing (if mechanical cause reported)	0	0	N/A	0	0
				33. Was this consist transporting passengers? (Y/N)   N	
34. Locomotive Units	a. Head End	b. Mid Train	c. Rear End	35. Cars	Loaded
		b. Manual	c. Remote		a. Freight
					b. Pass.
					c. Freight
					d. Pass.
					e. Caboose
(1) Total in Train	2	0	0	0	0
(2) Total Derailed	0	0	0	0	0
36. Equipment Damage This Consist   1009538		37. Track, Signal, Way, & Structure Damage   222815		38. Primary Cause Code T215	
				39. Contributing Cause Code H993	
40. Engineer/Operators N/A			41. Firemen 0		
			42. Conductors 1	43. Brakemen 0	
				44. Engineer/Operator Hrs 3 Mi 25	
				45. Conductor Hrs 3 Mi 25	
Casualties to:	46. Railroad Employees	47. Train Passengers	48. Other	49. EOT Device? 1. Yes 2. No   1	
Fatal	0	0	0	50. Was EOT Device Properly Armed? 1. Yes 2. No   1	
Nonfatal	N/A	0	0	51. Caboose Occupied by Crew? 1. Yes 2. No   N/A	
<b>OPERATING TRAIN #2</b>					
52. Type of Equipment Consist (single entry)		1. Freight train 2. Passenger train 3. Commuter train		4. Work train 5. Single car 6. Cut of cars	
		7. Yard/switching 8. Light loco(s). 9. Maint./inspect.car		A. Spec. MoW Equip. Code N/A	
				53. Was Equipment Attended? 1. Yes 2. No   N/A	
				54. Train Number/Symbol N/A	
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated   0 MPH   N/A		57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable

56. Trailing Tons (gross tonnage, excluding power units)		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking		i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits		o. Positive train control p. Other (Specify in narrative) Code(s)		2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A			
58. Principal Car/Unit		a. Initial and Number		b. Position in Train		c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.		Alcohol		Drugs			
(1) First involved (derailed, struck, etc)		0		N/A		N/A				N/A		N/A			
(2) Causing (if mechanical cause reported)		0		N/A		N/A		60. Was this consist transporting passengers? (Y/N)				N/A			
61. Locomotive Units		a. Head End		Mid Train b. Manual c. Remote		Rear End d. Manual c. Remote		62. Cars		Loaded a. Freight b. Pass.		Empty c. Freight d. Pass.		e. Caboose	
(1) Total in Train		0		0 0		0 0		(1) Total in Equipment Consist		0 0		0 0		0 0	
(2) Total Derailed		0		0 0		0 0		(2) Total Derailed		0 0		0 0		0 0	
63. Equipment Damage This Consist		0		64. Track, Signal, Way, & Structure Damage		0		65. Primary Cause Code		N/A		66. Contributing Cause Code		N/A	
Number of Crew Members						Length of Time on Duty									
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator		72. Conductor					
N/A		N/A		N/A		N/A		Hrs 0 Mi 0		Hrs 0 Mi 0					
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?		77. Was EOT Device Properly Armed?					
Fatal		0		0		0		1. Yes 2. No N/A		1. Yes 2. No N/A					
Nonfatal		0		0		0		78. Caboose Occupied by Crew?						N/A	
								1. Yes 2. No							
Highway User Involved						Rail Equipment Involved									
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment		3. Train (standing) 6. Light Loco(s) (moving)		Code					
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train(units pulling) 4. Car(s)(moving)		7. Light(s) (standing)		N/A					
B. Truck E. Van H. Motorcycle M. Other (spec. in narrative)				N/A		2. Train(units pushing) 5. Car(s)(standing)		8. Other (specify in narrative)		N/A					
80. Vehicle Speed (est. MPH at impact)		N/A		81. Direction geographical		Code		84. Position of Car Unit in Train		N/A					
				1. North 2. South 3. East 4. West		N/A									
82. Position				Code		85. Circumstance		Code							
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				N/A		1. Rail Equipment Struck Highway User		N/A							
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by		Code							
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither		N/A							
86c. State here the name and quantity of the hazardous materials released, if any.															
N/A															
87. Type of Crossing		1. Gates 4. Wig Wags		7. Crossbucks 10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code			
2. Cantilever FLS 5. Hwy. traffic signals 8. Stop signs 11. Other (spec. in narr.)		3. Standard FLS 6. Audible 9. Watchman 12. None				(See instructions for codes)		N/A		1. Yes 2. No 3. Unknown		N/A			
Code(s)		N/A N/A N/A		N/A N/A N/A N/A											
90. Location of Warning		Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code					
1. Both Sides				1. Yes 2. No 3. Unknown		N/A		1. Yes 2. No 3. Unknown		N/A					
2. Side of Vehicle Approach															
3. Opposite Side of Vehicle Approach		N/A													
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code			
N/A		1. Male 2. Female		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate 4. Stopped on Crossing		N/A			
										2. Stopped and then Proceeded 5. Other (specify in narrative)		N/A			
										3. Did not Stop					
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by (primary obstruction)		Code									
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation 7. Other (specify in narrative)		N/A									
				2. Standing Railroad Equipment 4. Topography 6. Highway Vehicle 8. Not obstructed											
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code			
		N/A		N/A		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A			
						102. Highway Vehicle Property Damage (est. dollar damage)		N/A		103. Total Number of Highway-Rail Crossing Users (include driver)		N/A			
104. Locomotive Auxiliary Lights?				Code		105. Locomotive Auxiliary Lights Operational?		Code							
1. Yes 2. No				N/A		1. Yes 2. No		N/A							
106. Locomotive Headlight Illuminated?				Code		107. Locomotive Audible Warning Sounded?		Code							
1. Yes 2. No				N/A		1. Yes 2. No		N/A							

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.  
88.bmp



#### 109. SYNOPSIS OF THE ACCIDENT

On October 5, 2005, at approximately 5:10 a.m., MDT, eastbound Union Pacific Railroad Company (UP) loaded coal Train Symbol CCDCB9-03, operating on Main Track No. 2, derailed 20 cars at Milepost (MP) 108.9 near Bridgeport, Nebraska, on the North Platte Service Unit, South Morrill Subdivision. The 104th through the 123rd car from the head-end of the train derailed. The South Morrill Subdivision extends between the O'Fallons (Milepost 0.0) and Horse Creek Stations (Milepost 165.5) in Nebraska, a distance of approximately 165 miles. The majority of the South Morrill subdivision is equipped with a Traffic Control System (TCS) supplemented by an on-board Automatic Cab Signal System (ACS).

In the immediate area of the derailment the track configuration consists of a double crossover between 2 main tracks at the Towers Station, at control point (CP) W109. The track grade is practically level. The weather conditions were dark and clear at the time with the temperature at 36 °F.

The train consisted of 2 locomotives, 127 loaded coal cars, 17,781 tons, and was 7,006 feet in length. At the time of the derailment, the train was traveling at a recorded speed of 47 mph in the vicinity of the double crossover switches on Main Track No. 2. The crew reported they encountered a "rough" spot while traveling on tangent track over the east crossover switch located at approximately MP 108.9.

Shortly after feeling the "rough" spot, the train experienced an undesired emergency application of the train air brakes. The crew reported this to the train dispatcher in Omaha, Nebraska. The engineer attempted to recover the train air brakes after the emergency application, but, the air hose separations on the derailed cars prevented him from doing so.

Monetary damages were \$1,009,538 for equipment and \$222,815 for track.

The probable cause of the derailment is broken joint bars. A contributing factor was the maintenance-of-way department's improper application of the bars on a composite transition rail.

#### 110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

##### Circumstances Prior to the Accident:

The crew of Train Symbol CCDCB9-03 went on duty at South Morrill Station, in Nebraska, at 1:45 a.m., after having received more than the required statutory off-duty time. The train consisted of 2 locomotives, 127 loaded coal cars, 7,006 feet in length, and was 17,181 tons. After receiving an initial air brake test, the train departed South Morrill at 2:45 a.m. and encountered no problems as they headed east towards North Platte, Nebraska. The engineer was seated at the controls on the south side of the leading locomotive; the conductor was seated on the north side as the train traversed the tangent portion of the east crossover switch on Main Track No. 2 at Towers Station, around 5:10 a.m. The weather conditions were dark and clear at the time with the temperature at 36 °F. The track grade is practically level.

##### The Accident:

The train was being operated at 47 mph (maximum speed for that train was 50 mph) when the crew felt a "bump or dip" in the track structure. The crew attempted to report this to the dispatcher in Omaha, via the radio, but were unsuccessful so they contacted him using a cellular telephone. At about the same time, a crew member from a train stopped on the Main Track No. 1 notified them they had cars derailed, and at that time, the crew on Train Symbol CCDCB9-03 experienced an undesired emergency application of the train brakes.

The 104th through 123rd cars of the train derailed causing an estimated \$1,009,538 damage to equipment and \$222,815 to the track and track structure.

##### Analysis and Conclusion:

The two crew members were transported to North Platte where they were administered FRA post-accident toxicological tests. All tests were negative. The speed at the point of derailment was determined to be 47 mph, which was within the 60 mph maximum speed limit. A broken joint bar with an old break, along with the attached portion of rail, was sent to the UP metallurgy laboratory in Omaha. The broken joint bar was later determined to be the cause of the derailment. The railroad was cited with one defect for applying the joint bars inappropriately.

##### Probable Cause:

The FRA determined the probable cause of this derailment to be a broken joint bars. A contributing factor was the maintenance-of-way department's improper application of the bars on a composite transition rail.

