



***Federal Railroad Administration  
Office of Safety  
Headquarters Assigned  
Accident Investigation Report  
HQ-2005-89***

***Norfolk Southern (NS)  
Davisboro, Georgia  
October 13, 2005***

***Note that 49 U.S.C. §20903 provides that no part of an accident or incident report made by the Secretary of Transportation/Federal Railroad Administration under 49 U.S.C. §20902 may be used in a civil action for damages resulting from a matter mentioned in the report.***

1. Name of Railroad Operating Train #1 Norfolk Southern Corp. [NS ]			1a. Alphabetic Code NS			1b. Railroad Accident/Incident No. 022701			
2. Name of Railroad Operating Train #2 N/A			2a. Alphabetic Code N/A			2b. Railroad Accident/Incident N/A			
3. Name of Railroad Responsible for Track Maintenance: Norfolk Southern Corp. [NS ]			3a. Alphabetic Code NS			3b. Railroad Accident/Incident No. 022701			
4. U.S. DOT_AAR Grade Crossing Identification Number			5. Date of Accident/Incident Month   Day   Year 10   13   2005			6. Time of Accident/Incident 02:25: <input checked="" type="checkbox"/> AM <input type="checkbox"/> PM			
7. Type of Accident/Incident (single entry in code box)			1. Derailment 2. Head on collision 3. Rear end collision			4. Side collision 5. Raking collision 6. Broken Train collision			
			7. Hwy-rail crossing 8. RR grade crossing 9. Obstruction			10. Explosion-detonation 11. Fire/violent rupture 12. Other impacts			
						13. Other (describe in narrative) 01			
8. Cars Carrying HAZMAT 0		9. HAZMAT Cars Damaged/Derailed 0		10. Cars Releasing HAZMAT 0		11. People Evacuated 0		12. Division Georgia	
13. Nearest City/Town Davisboro			14. Milepost (to nearest tenth) S124.5		15. State Abbr Code N/A   GA		16. County WASHINGTON		
17. Temperature (F) (specify if minus) 68 F		18. Visibility (single entry) 1. Dawn 3. Dusk 2. Day 4. Dark Code 4		19. Weather (single entry) 1. Clear 3. Rain 5. Sleet 2. Cloudy 4. Fog 6. Snow Code 2		20. Type of Track 1. Main 3. Siding 2. Yard 4. Industry Code 1			
21. Track Name/Number Savannah Main			22. FRA Track Code Class (1-9, X) 4		23. Annual Track Density (gross tons in millions) 32.9		24. Time Table Direction 1. North 3. East Code 3		
<b>OPERATING TRAIN #1</b>									
25. Type of Equipment Consist (single entry)			1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code 1		26. Was Equipment Attended? 1. Yes 2. No   1	
27. Train Number/Symbol 192G512									
28. Speed (recorded speed, if available) Code R - Recorded E - Estimated 49 MPH   R			30. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track c. Auto train stop i. Time table/train orders o. Positive train control d. Cab j. Track warrant control p. Other (Specify in narrative) Code(s) e. Traffic k. Direct traffic control f. Interlocking l. Yard limits			30a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable 2 = Remote control tower 3 = Remote control transmitter - more than one remotely controlled transmitter 0			
29. Trailing Tons (gross tonnage, excluding power units) 5710									
31. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded (yes/no)	32. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.				
(1) First involved (derailed, struck, etc)		N/A	13	yes	Alcohol		Drugs		
(2) Causing (if mechanical cause reported)		0	0	N/A	0		0		
33. Was this consist transporting passengers? (Y/N)					N				
34. Locomotive Units		a. Head End	b. Mid Train	c. Rear End	35. Cars		a. Freight	b. Pass.	
		d. Manual	e. Remote				c. Freight	d. Pass.	
							e. Caboose		
(1) Total in Train		2	0	0	(1) Total in Equipment Consist		41	0	
(2) Total Derailed		0	0	0	(2) Total Derailed		21	0	
							3	0	
							0	0	
36. Equipment Damage This Consist		37. Track, Signal, Way, & Structure Damage 18000		38. Primary Cause Code T207		39. Contributing Cause Code N/A			
Number of Crew Members				Length of Time on Duty					
40. Engineer/Operators 1		41. Firemen 0		42. Conductors 1		43. Brakemen 1		44. Engineer/Operator Hrs 4 Mi 55	
								45. Conductor Hrs 4 Mi 55	
Casualties to:		46. Railroad Employees		47. Train Passengers		48. Other		49. EOT Device?	
Fatal		0		0		0		1. Yes 2. No   1	
Nonfatal		N/A		0		0		50. Was EOT Device Properly Armed? 1. Yes 2. No   1	
								51. Caboose Occupied by Crew? 1. Yes 2. No   N/A	
<b>OPERATING TRAIN #2</b>									
52. Type of Equipment Consist (single entry)			1. Freight train 4. Work train 7. Yard/switching 2. Passenger train 5. Single car 8. Light loco(s). 3. Commuter train 6. Cut of cars 9. Maint./inspect.car			A. Spec. MoW Equip. Code N/A		53. Was Equipment Attended? 1. Yes 2. No   N/A	
54. Train Number/Symbol N/A									
55. Speed (recorded speed, if available) Code R - Recorded E - Estimated N/A MPH   N/A			57. Method(s) of Operation (enter code(s) that apply) a. ATCS g. Automatic block m. Special instructions b. Auto train control h. Current of traffic n. Other than main track			57a. Remotely Controlled Locomotive? 0 = Not a remotely controlled 1 = Remote control portable			

56. Trailing Tons ( <i>gross tonnage, excluding power units</i> )		N/A		c. Auto train stop d. Cab e. Traffic f. Interlocking	i. Time table/train orders j. Track warrant control k. Direct traffic control l. Yard limits	o. Positive train control p. Other ( <i>Specify in narrative</i> ) Code(s)					2 = Remote control tower 3 = Remote control transmitter - more than one remote control transmitter		N/A				
58. Principal Car/Unit		a. Initial and Number	b. Position in Train	c. Loaded(yes/no)		59. If railroad employee(s) tested for drug/alcohol use, enter the number that were positive in the appropriate box.							Alcohol	Drugs			
(1) First involved ( <i>derailed, struck, etc</i> )		N/A	N/A	N/A									N/A	N/A			
(2) Causing ( <i>if mechanical cause reported</i> )		N/A	N/A	N/A		60. Was this consist transporting passengers? (Y/N)							N/A				
61. Locomotive Units		a. Head End	Mid Train		Rear End		62. Cars			Loaded		Empty		e. Caboose			
			b. Manual	c. Remote	d. Manual	c. Remote				a. Freight	b. Pass.	c. Freight	d. Pass.				
(1) Total in Train		N/A	N/A	N/A	N/A	N/A	(1) Total in Equipment Consist			N/A	N/A	N/A	N/A	N/A			
(2) Total Derailed		N/A	N/A	N/A	N/A	N/A	(2) Total Derailed			N/A	N/A	N/A	N/A	N/A			
63. Equipment Damage This Consist		N/A		64. Track, Signal, Way, & Structure Damage		N/A		65. Primary Cause Code			N/A		66. Contributing Cause Code		N/A		
Number of Crew Members						Length of Time on Duty											
67. Engineer/Operators		68. Firemen		69. Conductors		70. Brakemen		71. Engineer/Operator			72. Conductor						
N/A		N/A		N/A		N/A		Hrs N/A Mi N/A			Hrs N/A Mi N/A						
Casualties to:		73. Railroad Employees		74. Train Passengers		75. Other		76. EOT Device?			77. Was EOT Device Properly Armed?						
Fatal		N/A		N/A		N/A		1. Yes 2. No N/A			1. Yes 2. No N/A						
Nonfatal		N/A		N/A		N/A		78. Caboose Occupied by Crew?			N/A						
								1. Yes 2. No									
Highway User Involved						Rail Equipment Involved											
79. Type		C. Truck-Trailer. F. Bus J. Other Motor Vehicle		Code		83. Equipment			3. Train ( <i>standing</i> )		6. Light Loco(s) ( <i>moving</i> )		Code				
A. Auto D. Pick-Up Truck G. School Bus K. Pedestrian				N/A		1. Train( <i>units pulling</i> )			4. Car(s)( <i>moving</i> )		7. Light(s) ( <i>standing</i> )		N/A				
B. Truck E. Van H. Motorcycle M. Other ( <i>spec. in narrative</i> )				N/A		2. Train( <i>units pushing</i> )			5. Car(s)( <i>standing</i> )		8. Other ( <i>specify in narrative</i> )		N/A				
80. Vehicle Speed ( <i>est. MPH at impact</i> )		N/A		81. Direction ( <i>geographical</i> )		Code		84. Position of Car Unit in Train						N/A			
				1. North 2. South 3. East 4. West		N/A											
82. Position				Code		85. Circumstance						Code					
1. Stalled on Crossing 2. Stopped on Crossing 3. Moving Over Crossing 4. Trapped				N/A		1. Rail Equipment Struck Highway User 2. Rail Equipment Struck by Highway User						N/A					
86a. Was the highway user and/or rail equipment involved in the impact transporting hazardous materials?				Code		86b. Was there a hazardous materials release by						Code					
1. Highway User 2. Rail Equipment 3. Both 4. Neither				N/A		1. Highway User 2. Rail Equipment 3. Both 4. Neither						N/A					
86c. State here the name and quantity of the hazardous materials released, if any.																	
N/A																	
87. Type of Crossing		1. Gates		4. Wig Wags		7. Crossbucks		10. Flagged by crew		88. Signaled Crossing Warning		Code		89. Whistle Ban		Code	
Warning		2. Cantilever FLS		5. Hwy. traffic signals		8. Stop signs		11. Other ( <i>spec. in narr.</i> )		Code		N/A		1. Yes		Code	
Code(s)		3. Standard FLS		6. Audible		9. Watchman		12. None		N/A		N/A		2. No		N/A	
		N/A		N/A		N/A		N/A						3. Unknown		N/A	
90. Location of Warning				Code		91. Crossing Warning Interconnected with Highway Signals		Code		92. Crossing Illuminated by Street Lights or Special Lights		Code					
1. Both Sides						1. Yes		N/A		1. Yes		N/A					
2. Side of Vehicle Approach						2. No				2. No							
3. Opposite Side of Vehicle Approach				N/A		3. Unknown				3. Unknown							
93. Driver's Age		94. Driver's Gender		Code		95. Driver Drove Behind or in Front of Train and Struck or was Struck by Second Train		Code		96. Driver		Code					
N/A		1. Male		N/A		1. Yes 2. No 3. Unknown		N/A		1. Drove around or thru the Gate		4. Stopped on Crossing					
		2. Female								2. Stopped and then Proceeded		5. Other ( <i>specify in narrative</i> )					
										3. Did not Stop							
97. Driver Passed Standing Highway Vehicle		Code		98. View of Track Obscured by ( <i>primary obstruction</i> )		Code		Code		7. Other ( <i>specify in narrative</i> )		Code					
1. Yes 2. No 3. Unknown		N/A		1. Permanent Structure 3. Passing Train 5. Vegetation		N/A		6. Highway Vehicle		8. Not obstructed		N/A					
				2. Standing Railroad Equipment 4. Topography													
101. Casualties to Highway-Rail Crossing Users		Killed		Injured		99. Driver Was		Code		100. Was Driver in the Vehicle?		Code					
		N/A		N/A		1. Killed 2. Injured 3. Uninjured		N/A		1. Yes 2. No		N/A					
						102. Highway Vehicle Property Damage ( <i>est. dollar damage</i> )		N/A		103. Total Number of Highway-Rail Crossing Users ( <i>include driver</i> )		N/A					
104. Locomotive Auxiliary Lights?						Code		105. Locomotive Auxiliary Lights Operational?		Code							
1. Yes 2. No						N/A		1. Yes 2. No		N/A							
106. Locomotive Headlight Illuminated?						Code		107. Locomotive Audible Warning Sounded?		Code							
1. Yes 2. No						N/A		1. Yes 2. No		N/A							

108. DRAW A SKETCH OF ACCIDENT AREA INCLUDING ALL TRACKS, SIGNALS, SWITCHES, STRUCTURES, OBJECTS, ETC., INVOLVED.



## 109. SYNOPSIS OF THE ACCIDENT

On October 13, 2005, at 2:25, a.m. Eastern Daylight Time (EDT), eastbound Norfolk Southern (NS) freight Train No. 192G512 derailed at milepost (MP) S124.5 on the Georgia Division, Savannah Subdivision, near Davisboro, Georgia (GA). The three man crew consisted of an engineer, conductor, and brakeman. They reported for duty on October 12, 2005, at 9:30 p.m. in Macon, GA. Train No. 192G512 consisted of two locomotives, NS8459 in the lead and NS2518 trailing, with 41 loaded and 13 empty cars, a total of 5,710 tons. Train No. 192G512 was en route to Augusta, GA.

Train No. 192G512 was traveling at a recorded speed of 49 miles per hour (mph) prior to the derailment. The train crew felt a twisting or jarring motion shortly before an emergency brakes application occurred at 2:25 a.m. When their train stopped, the conductor and brakeman walked the train and found only 12 cars. They climbed the rear car and instructed the engineer to shove back. They found 24 cars derailed about a half mile back.

There was no hazardous material involved and no injuries to the train crew. Equipment damage was \$851,900 and \$18,000 in track damages.

At the time of the derailment, it was dark and cloudy with a slight breeze. The temperature was 68F.

The probable cause of the accident was a broken rail.

## 110. NARRATIVE

The following information was obtained from an investigation that was conducted by the Federal Railroad Administration.

## Circumstances prior to the Accident

The crew of Train No. 192G512 included a locomotive engineer, conductor, and brakeman. They went on duty at 9:30 p.m. EDT, on October 12, 2005, at Brosnan Yard in Macon, Georgia, their home terminal. All crew members received more than their statutory time off period, 10 hours 38 minutes, prior to reporting for duty. The mixed freight train consisted of two locomotives, NS8459 in the lead with NS2518 trailing, 41 loaded cars, 13 empty cars for a total of 5,710 tons. The train, destined for Augusta, GA, received an initial terminal train air brake test at 10:55 p.m. and departed Macon, GA. The trip was uneventful for the next 55 miles where they arrived at Tennille, GA, MP S134. At 1:54 a.m., NS dispatcher issued track authority 5541, directing Train No. 192G512 to proceed on the Savannah Subdivision from Tennille East, MP S134 to Millen West, MP S79.6. As the eastbound train approached MP S121, the locomotive engineer was seated at the controls in lead Locomotive No. NS8459, the conductor was seated on the opposite side of the lead locomotive, and the brakeman was seated in the trailing Locomotive No. NS2518. Train No. 192G512 was traveling at a recorded speed of 49 mph, the maximum allowed as designated in the current NS Timetable. Approaching the accident site from the west, the main line is tangent for three and a half miles and remains tangent for one mile beyond. The grade of the main line is 0.22-percent descending in the direction of the movement.

The NS timetable direction of Train No. 192G512 was east. Timetable direction is used for this report.

## The Accident

All three members of the train crew said they felt a twisting or jarring motion in the locomotives after they passed over a trailing switch at MP S124.5. At 2:25 a.m., the engineer said Train No. 192G512 had an undesired brake application. The conductor and brakeman walked back to inspect the train finding only 12 cars behind the locomotives. The conductor notified the dispatcher about the derailment. The conductor and brakeman climbed aboard the rear car and had the engineer reverse the train about one-half mile where they located the derailed cars. There were 21 loads and three empties derailed in accordion style. The first two cars resting on their sides, the other 22 cars remained upright. One additional car, a loaded hopper car was

damaged, but still on the track. The derailed and damaged cars were 14 tank cars of Kaolin Slurry, two covered hoppers carrying dry Kaolin, four open hoppers carrying Wood Chips, three asphalt residue cars, and one damaged tank car.

No injuries were sustained by the train crew, and no hazardous material was involved.

#### Analysis and Conclusions

After the derailment, Federal Railroad Administration (FRA) partnered with the NS maintenance of way department in conducting an inspection of the derailment site. The investigation revealed no defective conditions for surface, crossties, or drainage. The ballast was clean and there was no indication of either crosslevel or profile defects. During the site investigation, a 42-inch broken rail was found. The rail ends of the broken rail were battered and contained uncapped shells. Directly below these shelly marks is where the rail vertically broke. A walking inspection was conducted between MP S128 and MP S123.5 for additional rail defects, but none were found.

FRA reviewed the NS Savannah Subdivision rail reports for 2005. The Savannah Subdivision has 115 pound welded rail, which is inspected by NS for internal defects at four month intervals. On June 1, 2005, the main line was inspected with Detector Car No. RTC9. The report showed one defective weld was found by their detector car about five hundred feet west of this derailment. However, the defective weld was repaired with a replacement rail. NS 2005 Geometry Car reports were also reviewed. The last test on the Savannah Subdivision was September 15, 2005, and no defects were detected in the area of the derailment.

NS track inspections were also reviewed at NS Division Headquarters. Reports indicated track inspections were being performed according to regulations for the class of track on the Savannah Subdivision. The last three inspection reports dated October 4, October 6, and October 11, 2005, indicated no defects were noted by NS at the derailment site location.

The train crew was in compliance with NS Operating Rules and at operating within FRA allowable speed.

#### Probable Cause

Based upon the NS and FRA investigation a 42-inch piece of rail broke out vertically under load, underneath uncapped shells in the rail head. The missing piece of rail allowed the wheels to fall off one end and hit the other end at a speed which caused the cars to derail in the accordion style.